

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 5 77 WEST JACKSON BOULEVARD CHICAGO, ILLINOIS 60604

DATE:

AUG 2 1 2018

SUBJECT:

CLEAN AIR ACT INSPECTION REPORT

Lincolnland Agri-Energy, LLC

FROM:

Gregory Gehrig, Environmental Engineer

AECAB (MI/WI)

THRU:

Sarah Marshall, Section Chief

AECAB (MI/WI)

TO:

File

BASIC INFORMATION

Facility Name: Lincolnland Agri-Energy, LLC

Facility Location: 10406 North 1725th St, Palestine, IL

Date of Inspection: July 23, 2018

Lead Inspector: Gregory Gehrig, Environmental Engineer

Other Attendees: Dakota Prentice, Environmental Engineer, U.S. EPA; Mark Riggs, EHS and Compliance Manager, Lincolnland Agri-Energy, LLC

Contact Email: mriggs@lincolnlandagrienergy.com

Purpose of Inspection: CAA Compliance

Facility Type: Ethanol production from corn

Regulations Central to Inspection: SIP, NSPS and MACT

Arrival Time: 1300 hrs **Departure Time:** 1450 hrs

Inspection Type:

☐ Announced Inspection

Facility Name: Lincolnland Agri-Energy, LLC

Facility Location: 10406 North 1725th St, Palestine, IL

Date of Inspection: July 23, 2018

OPENING CONFERENCE

☐ CBI warning to facility provided

The following information was obtained verbally from facility personnel.

Company Ownership: Same ownership since at least 2013.

Process Description:

Lincolnland Agri-Energy, LLC (Lincolnland) has the permitted capacity to produce 70 million gallons per year (mmgpy) of ethanol from corn and is currently operating around 60 mmgpy. They also produce distillers dried grains (DDGS). The facility was designed by ICM and built by Fegan. They have five fermentors, one beer well and one associated scrubber for pollution control. Lincolnland uses one recuperative thermal oxidizer (RTO) to control emissions from the mash drying operations conducted to DDGS.

TOUR INFORMATION

EPA toured the facility: Yes

Data Collected and Observations:

FLIR video was taken of volatile organic compound (VOC) emission points and possible VOC emission points. Lincolnland was operating normally during the facility tour. The following was observed during the tour:

- Control room, where air pollution control readings were collected.
- Scrubber, which was operating at a pressure differential of 27.4 inches of water and additive flow rate of 15 gallon per day.
- A pre-condenser to the scrubber, which was operating at an inlet pressure of 16.5 inches of water.
- Fermentors and beer well, where VOCs were observed venting uncontrolled from some agitators.
- Distillation/molecular sieves.
- RTO, which was operating at 1,440 °F.

Field Measurements: were not taken during this inspection.

RECORDS REVIEW

- Semi-Annual LDAR report for January 1 to June 30, 2018 (taken)
- Facility diagram (taken)

Facility Name: Lincolnland Agri-Energy, LLC

Facility Location: 10406 North 1725th St, Palestine, IL

Date of Inspection: July 23, 2018

CLOSING CONFERENCE

Requested documents:

None

Compliance Assistance: EPA indicated that Lincolnland should fully investigate and mitigate uncontrolled venting from agitators on top of the fermentors.

Concerns: Uncontrolled venting from agitators on top of the fermentors.

SIGNATURES

Lead Inspector:

Date:

Section Chief:

h Date

Facility Name: Lincolnland Agri-Energy, LLC Facility Location: 10406 North 1725th St, Palestine, IL Date of Inspection: July 23, 2018

APPENDIX A: DIGITAL IMAGE LOG

1. Inspector Name:	2. Date(s) of Inspection:
Gregory Gehrig	July 23, 2018
3. Company/Facility Name:	4. Street Address, City, State:
Lincolnland Agri-Energy, LLC	10406 North 1725th St, Palestine, IL
5. Number of Images:	6. Archival Record Location:
7	CD-R labeled Lincolnland Images 7.23.2018

Image name	Date and Time (CDT)	Description
MOV_1986*	July 23, 2018 at 1413	FLIR video of scrubber outlet; components on beer well and Ferm #3, Ferm #5 and Ferm #4. Venting agitators on beer well, Ferm #5, and Ferm #4.
MOV_1987*	July 23, 2018 at 1419	FLIR video of components on Ferm #1 and Ferm #2; and venting agitator on Ferm #2.
IMG 0103	July 23, 2018 at 1349	Photo of RTO stack.
IMG_0104	July 23, 2018 at 1410	Photo of fermentation scrubber.
IMG_0105	July 23, 2018 at 1413	Photo of Ferm #1.
IMG 0106	July 23, 2018 at 1417	Photo of pressure relief conservation vent on Ferm #3.
IMG_0107	July 23, 2018 at 1419	Photo of pressure relief conservation vent on Ferm #3, noting clean in place residue.

^{*}FLIR camera time signature incorrect, but date and time listed above are accurate.